

IECEx Quality Assessment Report Summary

Audit date: 2024-08-01

INTERNATIONAL ELECTROTECHNICAL COMMISSION **IEC Certification System for Explosive Atmospheres**

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: GB/SIR/QAR09.0012/15 Page 1 of 1

80213049 / 80213050 / 80213051 / 80213052 QAR Free Ref. No.: Status: Issued

Details of change: Recertification Audit Date of issue: 2024-08-06

Location(s) audited: **ADS LLC** Valid until:2027-08-13 340 The Bridge Street

> Suite 204 Huntsville Alabama 35806

USA

United States of America

Issuing ExCB: **CSAE - CSA Group Testing UK Ltd**

Manufacturer: **ADS LLC**

340 The Bridge Street

Suite 204 Huntsville Alabama 35806

USA

United States of America Location of

Manufacturer:

Product information: Sensors, transducers and signalling switches, instrumentation, measurement and control equipment.

Type of protection: Ex ia, ib

Related QARs:

GB/SIR/QAR09.0012/00 GB/SIR/QAR09.0012/01 GB/SIR/QAR09.0012/02 GB/SIR/QAR09.0012/03 GB/SIR/QAR09.0012/04 GB/SIR/QAR09.0012/05 GB/SIR/QAR09.0012/08 GB/SIR/QAR09.0012/06 GB/SIR/QAR09.0012/07 GB/SIR/QAR09.0012/09 GB/SIR/QAR09.0012/10 GB/SIR/QAR09.0012/11 GB/SIR/QAR09.0012/12 GB/SIR/QAR09.0012/13 GB/SIR/QAR09.0012/14

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEX SIR 09.0020X issue: 0 IECEX SIR 09.0020X issue: 3 IECEX SIR 09.0020X issue: 6 IECEX SIR 09.0020X issue: 9 IECEX SIR 09.0020X issue: 12 IECEX SIR 09.0020X issue: 15 IECEX SIR 09.0020X issue: 18 IECEX SIR 09.0020X issue: 21	IECEX SIR 09.0020X issue: 1 IECEX SIR 09.0020X issue: 4 IECEX SIR 09.0020X issue: 7 IECEX SIR 09.0020X issue: 10 IECEX SIR 09.0020X issue: 13 IECEX SIR 09.0020X issue: 16 IECEX SIR 09.0020X issue: 19 IECEX SIR 09.0021X issue: 0	IECEX SIR 09.0020X issue: 2 IECEX SIR 09.0020X issue: 5 IECEX SIR 09.0020X issue: 8 IECEX SIR 09.0020X issue: 11 IECEX SIR 09.0020X issue: 14 IECEX SIR 09.0020X issue: 17 IECEX SIR 09.0020X issue: 20 IECEX SIR 09.0021X issue: 1

Comments: